

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

1053208-011802



Fig. 1

PRIOR ART

20870" 802500T




Fig. 2

PRIOR ART

20870-802507




Fig. 3

PRIOR ART

208TFO" 802E500F




Fig. 4

208T-082500T




Fig. 5

Effect of Calcium on 7050 Ingot Cracking - No Beryllium Grain Refined with Ti-B




Fig. 6a

Effect of Calcium on 7050 Ingot Cracking - No Beryllium Grain Refined with Ti-C




Fig. 6b

The Effect of Additives on Al-5Mg Melt Oxidation




Fig. 7